## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L2	12	(((land or pad or trace) with (plurality or many or several) with (through-hole or hole or opening) with fill\$3 with solder\$3) and ((metal\$3 or conductive) with (plate or substrate))).clm.	US-PGPUB	OR	ON	2008/02/13 12:09
L3	94	((land or pad or trace) with (plurality or many or several) with (through-hole or hole or opening) with fill\$3 with solder\$3) and ((metal\$3 or conductive) with (plate or substrate))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/13 12:11

2/13/2008 12:17:49 PM

C:\ Documents and Settings\ cprasad\ My Documents\ EAST\ workspaces\ default.wsp